





NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

SKYLAB 1-2 ON-BOARD PHOTO—This excellent view of the Skylab 1 space station cluster in Earth orbit was taken from the Skylab 2 Command/Service Module during the final “fly around” inspection of the CSM. Clouds over water are in the background. Note the deployed parasol solar shield which shades the Orbital Workshop where the micrometeoroid shield is missing. The one remaining OWS solar array system wing has been fully deployed successfully. The OWS solar panel on the opposite side is completely missing.